



Reminder – anchoring in Malaysian waters off East Johor

Over the years, several vessels entered with Gard have been detained and fined by the Malaysian Maritime Enforcement Agency for anchoring in East Johor waters without the requisite permissions from the authorities.

Published 15 August 2024

The information provided in this article is intended for general information only. While every effort has been made to ensure the accuracy of the information at the time of publication, no warranty or representation is made regarding its completeness or timeliness. The content in this article does not constitute professional advice, and any reliance on such information is strictly at your own risk. Gard AS, including its affiliated companies, agents and employees, shall not be held liable for any loss, expense, or damage of any kind whatsoever arising from reliance on the information provided, irrespective of whether it is sourced from Gard AS, its shareholders, correspondents, or other contributors.

Malaysian authorities conducted a special operation, “Jangkar Haram” in 2021, targeting ships that had anchored in waters off East Johor, without prior written permission from the Director General of the Malaysian Marine Department. Even three years later, arrests of such vessels continue.

Extent of Malaysian waters off East Johor

In nearly all the cases Gard has handled, mariners had mistakenly understood their anchoring position to be outside Malaysian territorial waters. As our correspondent, Spica, reports in their [circular](#) these waters are sometimes referred to as Singapore OPL East, or sometimes even International waters.



The Malaysian governing law which sets out the limits of its territorial waters is the Territorial Sea Act 2012 (TSA). To determine if a vessel has entered Malaysian territorial waters, the Malaysian Maritime Enforcement Agency (MMEA) and the Marine Department of Malaysia rely on the “1979 Territorial Waters Chart”. Below is an image of this chart to illustrate the area within which vessels have been detained, which is shaded in blue in the below chart. This area may not be marked on the navigational charts commonly used by merchant vessels and this has contributed to a lack of clarity amongst mariners. As such, vessels are advised to obtain a copy of the Malaysian “1979 Territorial Waters Chart” through their local agents.

All the recent detentions have been under section 491B(1) of the Malaysian Merchant Shipping Ordinance 1952 (MSO). This section stipulates that ships must notify the Director of Marine of activities within Malaysian waters whenever engaging in various activities. The relevant provision in this section under which vessels have been detained by the MMEA is 491B(1)(L) which is a sweep-up provision, requiring approval be obtained for “any other activity as determined by the Director of Marine”. The provision is widely worded, which makes it difficult to challenge.

The information provided in this article is intended for general information only. While every effort has been made to ensure the accuracy of the information at the time of publication, no warranty or representation is made regarding its completeness or accuracy. The information is provided on an “as is” basis and should not be relied upon for legal or other purposes. Gard AS, including its affiliated companies, agents and employees, shall not be held liable for any loss, expense, or damage of any kind whatsoever arising from reliance on the information provided, irrespective of whether it is sourced from Gard AS, its shareholders, correspondents, or other contributors.

Malaysian Shipping Notice no. [05/2014](#) aims to clarify the definition of “any other activity” to include the following: laying up; welding and other hot works; anchoring in a non-anchorage; and any form of underwater operations. The effect of this Notice is that it is now more difficult for owners of detained vessels to argue that they were not aware of the fact that permission was needed prior anchoring.

We have previously also seen vessels being detained by the MMEA for alleged non-payment of light dues. Section 3(1) of the Federation Light Dues Act 1953 requires the owner, agent or master of every ship which visits any port or place within Peninsular Malaysia to pay light dues.

Detention and statement taking of crew

Once a vessel has been detained, Owners can expect the following investigative steps to be taken by the MMEA:

1. The Master and Chief Officer/Chief Engineer are usually taken ashore to MMEA's office to give their statements.
2. The Master and Chief Officer/Chief Engineer can expect to be questioned about their qualifications and experience, voyage details, and the reasons for anchoring at that specific location etc.
3. The crew's passports and ship's documents are also confiscated by MMEA.

Owners will have to appoint a local Malaysian agent, and it is recommended that owner's representative (local agent, correspondent, or a lawyer) accompanies the crew member when the statement is being taken by the MMEA investigating officer. An owners' local representative would be able to assist with translating the questions asked by the investigating officer into English, as well as deal with the authorities on behalf of the owners.

We understand that the investigation could take anywhere between 1-3 days, or even longer and owners may have to make arrangements, through their local agents, for overnight stay of the Master ashore.

Getting the vessel released

Once statements have been taken from the crew, MMEA will hand the case over to the Marine Department. For the purposes of securing the release of the vessel a hearing may be fixed before the magistrate. Owners usually will be represented by a lawyer at the hearing and will be required to pay a bond to release the vessel under section 413 of the Criminal Procedure Code (CPC). A bond is a security paid by owners for the release of the vessel, as security for a fine or compound to be set at a later date. The bond is paid by a fixed deposit through opening an account under the name of the Court appointed bailor usually the local agent.

Once the bond is paid and ship's documents returned to the vessel, the vessel can be released.

released. Thereafter, a decision can be taken whether to admit liability and pay the compound, i.e., pay a lower penalty in exchange for admitting liability for the charges, or dispute the charges. The maximum fine for each offence is MYR 100,000 (approximately USD 24,000).

The entire process of getting the vessel released can take anything from a few days to a few weeks.

Recommendations

- Vessels are advised to obtain a copy of the Malaysian “1979 Territorial Waters Chart” through their local agents.
- If anchoring in locations within the purported boundaries of the 1979 Territorial Waters Chart, it is advised that owners appoint a local agent in Malaysia. Gard has been informed that the Marine Department of Malaysia has established dedicated lay-up anchorages in waters off East Johor. Owners can contact their local agents for further information.
- Mariners must check with the appointed local agents that the Director of Marine has been informed before anchoring and written permission obtained.
- Fines of this nature may not be covered by Gard under P&I Rule 47 and therefore could fall outside P&I cover. That being said, if a vessel is detained or arrested, we encourage Members to contact Gard for assistance.

Such detentions can also lead to commercial disputes between owners and charterers. Reference can be made to our article [‘Double-check where you can anchor – lessons from the AFRA OAK decision’](#). It is worth mentioning that over the past few years several vessels have also been arrested for illegal anchoring in the Indonesian archipelago by its navy. Please see our alert [‘Vessel detentions for illegal anchoring in Indonesian waters’](#) for further information.

We would like to thank Jeremy Joseph and Matthew Van Huizen of Joseph & Partners for their contribution to this alert.

The information provided in this article is intended for general information only. While every effort has been made to ensure the accuracy of the information at the time of publication, no warranty or representation is made regarding its completeness or timeliness. The content in this article does not constitute professional advice, and any reliance on such information is strictly at your own risk. Gard AS, including its affiliated companies, agents and employees, shall not be held liable for any loss, expense, or damage of any kind whatsoever arising from reliance on the information provided, irrespective of whether it is sourced from Gard AS, its shareholders, correspondents, or other contributors.