



Risk of collision with offshore installations from attendant vessels

A recent increase in incidents involving attendant ships colliding with offshore oil and gas, and renewable energy structures has led the UK's Health and Safety Executive (HSE) to issue a safety notice focusing on the causes of such incidents.

Published 02 April 2025

The information provided in this article is intended for general information only. While every effort has been made to ensure the accuracy of the information at the time of publication, no warranty or representation is made regarding its completeness or timeliness. The content in this article does not constitute professional advice, and any reliance on such information is strictly at your own risk. Gard AS, including its affiliated companies, agents and employees, shall not be held liable for any loss, expense, or damage of any kind whatsoever arising from reliance on the information provided, irrespective of whether it is sourced from Gard AS, its shareholders, correspondents, or other contributors.

Background

Collisions happen because personnel responsible for watchkeeping and the safe navigation of vessels are distracted by non-navigational tasks, meaning situational awareness is not properly maintained, combined with insufficient communication among the bridge team. These factors have led to an increase in collisions or near-misses, highlighting the need for improved navigational watch processes and systems.

Any incidents involving human failure, should not blame the individual, but rather, the failure should be addressed in the risk management systems implemented onboard. Measures should be taken to address the technical systems, operating procedures and organisational factors that increase the likelihood of human failures ([performance influencing factors](#)) and, to detect and correct these before any adverse consequences occur.

This is consistent with the requirements set out in international maritime conventions – notably SOLAS (Safety of Life at Sea) Convention Chapter V, Regulation 15.

Many investigations into navigation incidents list “human error” as the root cause of the incident. It is rare that an investigator tries to reconstruct the incident to fully understand the circumstances that lead to the incident. This way, investigations can miss entirely the underlying and dynamic problems of navigating a vessel in a particular environment.

The below case studies [presented by the UK HSE](#), highlights the critical issues leading up to the human failures faced by vessels engaged in operations connected with offshore installations and windfarms over the past five years.

Case 1 - Loss of situational awareness and distracted by administrative tasks

en-US

Case 2 - Failure to keep a proper lookout

en-US

Case 3 - Failure to assess environmental conditions

en-US

Case 4 - Lack of communication between the bridge team

en-US

Recommendations

Vessel operators and duty holders responsible for marine activities connected with offshore oil and gas installations, and windfarms should review operating procedures and take actions relevant to their operations. Key recommendations include:

Provide clear watchkeeping instructions

International Maritime Organisation (IMO) standards require a proper lookout to be maintained at all times. The lookout must focus solely on watchkeeping, with no other duties assigned. This applies when the vessel is engaged in a connected activity, including when outside the 500m zone on standby or transiting through a windfarm. Watchkeeping arrangements during these times should be reviewed against IMO standards and the International Regulations for Preventing Collisions at Sea to ensure all principles for keeping a navigational watch are applied. Ensure watchkeeping procedures and instructions for connected activities are clear and include periods when the vessel is on standby or transiting through a windfarm.

Review bridge resource management

Vessel operators should review bridge resource management (BRM) processes. Check the effectiveness of bridge teamwork and communication arrangements, including how the culture of challenging actions and omissions by any member of the bridge team is dealt with. Review the design, arrangement and use of bridge equipment, including electronic aids, automated functions and dynamic positioning (DP) systems, and the effectiveness of BRM training. BRM training is a behavioural tool which assists with the development of teamwork, and as such adds to existing competency assurance programs that aim to establish and maintain individual competency.

Review the use of bridge alarms

All cargo ships of 150GT or more must have a Bridge Navigational Watch Alarm System (BNWAS) to monitor bridge activity and alert the master if the OOW becomes incapacitated. The IMO's performance standards for BNWAS include an automatic function, operational only when a ship's heading or track control is activated.

However, the Safety of Life at Sea (SOLAS) Convention, Chapter V, Regulation 19 requires BNWAS to be ON and operating whenever a vessel is underway at sea. Duty holders and vessel operators should ensure BNWAS is always operational during connected activities or when standing by an installation. BNWAS alarms can be set between 3- and 12-minute intervals.

Operators should consider the proximity of attendant vessels to installations and select the appropriate interval, considering the distance a vessel may drift. Consider implementing new technologies, such as proximity warnings audible to bridge personnel when approaching an installation. These systems are already used on some windfarm vessels.

Monitor attendant vessels

Duty holders should ensure arrangements for monitoring attendant vessels can detect unplanned approaches to installations. Consider using an ERRV or automated systems like AIS tracking, guard zones, and alerts. If using an ERRV, the master and officers must understand their monitoring duties and have adequate resources and equipment visible from the watchkeeper's position.

Automated systems should be tested regularly to ensure they provide necessary alerts at appropriate ranges and Closest Point of Approach (CPA). Position vessels on standby at a distance from installations to make unplanned movements discernible and allow time for remedial action.

Consider sailing audits for marine assurance

In all cases described in this safety notice, duty holders chartering the vessels had a marine assurance process to verify the vessel's operational capability and crew competence. However, incidents highlight that a shore-based assurance process, where the vessel is visited while in port, may not be adequate to identify watchkeeping and bridge resource management bad practices.

These issues may only become apparent when the vessel is operating. Therefore, duty holders should consider the benefits of sailing audits, where a qualified and experienced assessor can identify bad practices and coach good practices.

Final comments

Gard's mission is to prevent losses by learning from past incidents and addressing the underlying causes of errors through a "just culture" approach. Accidents are very seldom caused by a single person and needs to be seen in a holistic way in the context of the whole ship's systems, crew and company organization!

The information provided in this article is intended for general information only. While every effort has been made to ensure the accuracy of the information at the time of publication, no warranty or representation is made regarding its completeness or timeliness. The content in this article does not constitute professional advice, and any reliance on such information is strictly at your own risk. Gard AS, including its affiliated companies, agents and employees, shall not be held liable for any loss, expense, or damage of any kind whatsoever arising from reliance on the information provided, irrespective of whether it is sourced from Gard AS, its shareholders, correspondents, or other contributors.