

# Contamination by cargo vapours.

Remember vapour line isolation for incompatible cargoes.