

Risk of collision.

Large bearing change at close range may still result in a close-quarter situation, or risk of collision.

