



Case study 4



Close up of the area where the vessel grounded on an uncharted obstruction



AIS tracks of some of the vessels with a draft between 14 and 15 meters which transited between Makassar Strait and North East Java Sea in the 2 month period before the date of incident